

Hunter NoSub		Need Sensor Backflow		Water Meter No		Rotor Mins		Spray Mins		Drip Mins		PROG A _____				PROG B _____				PROG C _____				PROG D _____				
CLOCK - STATION				CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE-CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
Totals						1			1			1					1			2	1							

1 11

1 Rotor-Back yard																									
2 Spray-Right side																									
3 Rotor-Front right																									
4 Spray-Front left																		1	1						

#50180 INSPECTION
Repair Plan Page #2 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

2 25

[illegible]

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____				PROG B _____				PROG C _____				PROG D _____								
CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER	
3 37																										
1 Rotor-Front right																										
2 Spray-Front right									1																	
3 Rotor-Back yard																										
4 Spray-Left side															1			1								

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Repair Plan Page #4 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

4 49

[illegible]

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Repair Plan Page #5 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

5 66

[illegible]

#50180 INSPECTION
Repair Plan Page #6 | 04/21/2026

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

6 52

[illegible]

#50180 INSPECTION
Repair Plan Page #7 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

7 40

[illegible]

#50180 INSPECTION
Repair Plan Page #8 | 04/21/2026

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

[illegible]

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Repair Plan Page #9 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

9 75

[illegible]

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Repair Plan Page #10 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2" VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

10 89

[illegible]

#50180 INSPECTION
Repair Plan Page #11 | 04/21/2026

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

[illegible]

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Repair Plan Page #12 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

18 22

[illegible]

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Repair Plan Page #13 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	--------------	--------------	--------------	--------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	-------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

19 66

1 Rotor-Back yard																									
2 Rotor-Front left																									
3 Rotor-Back yard																									
4 -Front right and back																									
5 -Left side																									

Totals			1			1			1						1			2	1						
--------	--	--	---	--	--	---	--	--	---	--	--	--	--	--	---	--	--	---	---	--	--	--	--	--	--

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A	PROG B	PROG C	PROG D
-----------------	-------------------------	-------------------	------------	------------	-----------	--------	--------	--------	--------

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	-------------------------------	--------------	-------------

Totals									Totals
--------	--	--	--	--	--	--	--	--	--------

1 1 1

1 Rotor-Back yard									
2 Spray-Right side									
3 Rotor-Front right									
4 Spray-Front left									Zone 4 did not fire wire locate and solenoid

#50180 INSPECTION
Coverage Plan Page #15 | 04/21/2026

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	----------------------------	--------------	-------------

1 Rotor-Right side									
2 Rotor-Front right									
3 Rotor-Back yard									
4 Spray-front left									

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Coverage Plan Page #16 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	--------------	--------------	--------------	--------------

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	-------------------------------	--------------	-------------

3 37

1 Rotor-Front right									
2 Spray-Front right									Missing rotor head gushing out water
3 Rotor-Back yard									
4 Spray-Left side									Bad valve not opening all the way to allow water to come through properly

#50180 INSPECTION
Coverage Plan Page #17 | 04/21/2026

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	----------------------------	--------------	-------------

1 Rotor-Left back									
2 Rotor-Back yard									
3 Spray-Right side									
4 Rotor-Front right									
5 Rotor-Left side									

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Coverage Plan Page #18 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	-------------------------------	--------------	-------------

5 66

1 Rotor-Back yard behind fence									
2 Rotor-Front left yard									
3 -No zone									
4 -Right side yard									One head broken gushing water one nozzle not spraying properly
5 -Front bed									
6 -No zone									

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Coverage Plan Page #20 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	-----------	------------	-----------	-------------	-------------	--------------	----------------------	-----------	-------------

7 40

1 Spray-Front left									
2 Rotor-Front left and Back yard									
3 Rotor-Back yard									
4 Spray-Right side									

#50180 INSPECTION
Coverage Plan Page #21 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	-------------------------------	--------------	-------------

1 Rotor-Front left									
2 Rotor-Back yard									
3 Spray-Front right									
4 Rotor-Right side									

#50180 INSPECTION
Coverage Plan Page #22 | 04/21/2026

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	----------------------------	--------------	-------------

1 Spray-Right side									
2 Rotor-Right side									
3 Spray-Left side									
4 Rotor-Back yard									

Alma Farms- Charlie Circle
300 Peachtree Rd, Hoschton

#50180 INSPECTION
Coverage Plan Page #26 | 04/21/2026

Hunter NoSub	Need Sensor Backflow	Water Meter No	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-----------------	-------------------------	-------------------	------------	------------	-----------	-----------------	-----------------	-----------------	-----------------

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	----------------------------	--------------	-------------

19 66

1 Rotor-Back yard									
2 Rotor-Front left									
3 Rotor-Back yard									
4 -Front right and back									
5 -Left side									

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	-------------------------------	--------------	-------------

[illegible]

1-4 Front left - Zone 4 did not fire wire locate and solenoid

3-2 Front right - Missing rotor head gushing out water

3-4 Left side - Bad valve not opening all the way to allow water to come through properly

5-4 Right side yard - One head broken gushing water one nozzle not spraying properly