

110 North
3102 Autumn Leaf Dr, Friendswood

#50015 INSPECTION
Repair Plan Page #1 | 04/09/2026

[illegible]

1 One

[illegible]

2 Two

[illegible]

7 Seven

[illegible][illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#50015 INSPECTION
Coverage Plan Page #2 | 04/09/2026

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
Totals					1				Totals

7 Seven

1 -					1				
-----	--	--	--	--	---	--	--	--	--


CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
Totals					1				Totals

110 North
3102 Autumn Leaf Dr, Friendswood

#50015 INSPECTION
Zone Photos | Page #3

ZONE INSPECTION PHOTOS

Controller 7 - Seven
Zone 1:
GPS: 29.5152521788, -95.1606255604



110 North
3102 Autumn Leaf Dr, Friendswood

#50015 INSPECTION
Zone Photos | Page #4

ZONE INSPECTION PHOTOS (continued)

Controller 7 - Seven

Zone 1:

GPS: 29.5154197849, -95.1605087764

