

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #1 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00 <u>T</u> <u>H</u> <u>S</u> <u> </u>	PROG B 01:00:00 <u> </u> <u>W</u> <u>F</u> <u> </u>	PROG C 01:00:00 <u> </u> <u> </u> <u> </u> <u> </u>	PROG D 01:00:00 <u> </u> <u> </u> <u> </u> <u> </u>
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	---	--	--	--

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2" VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

Totals			17	8	30	24	19	35	39	37	51	34	83	48	36	26	21	20	21	16	7	2	1		
--------	--	--	----	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	---	---	---	--	--

1 One

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #2 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00 _T_H_S_	PROG B 01:00:00 __W_F__	PROG C 01:00:00 _____	PROG D 01:00:00 _____
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	----------------------------	----------------------------	--------------------------	--------------------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2" VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

2 Two

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #3 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00 _T_H_S_	PROG B 01:00:00 __W_F__	PROG C 01:00:00 _____	PROG D 01:00:00 _____
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	----------------------------	----------------------------	--------------------------	--------------------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

3 Three

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #4 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00 _T_H_S_	PROG B 01:00:00 __W_F__	PROG C 01:00:00 _____	PROG D 01:00:00 _____
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	----------------------------	----------------------------	--------------------------	--------------------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

4 Four

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #5 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00 _T_H_S_	PROG B 01:00:00 __W_F__	PROG C 01:00:00 _____	PROG D 01:00:00 _____
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	----------------------------	----------------------------	--------------------------	--------------------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2" VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

5 Five

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #6 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00 _T_H_S_	PROG B 01:00:00 __W_F__	PROG C 01:00:00 _____	PROG D 01:00:00 _____
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	----------------------------	----------------------------	--------------------------	--------------------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2" VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

6 Six

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #7 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00 _T_H_S_	PROG B 01:00:00 __W_F__	PROG C 01:00:00 _____	PROG D 01:00:00 _____
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	----------------------------	----------------------------	--------------------------	--------------------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

8 Eight

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #8 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00 _T_H_S_	PROG B 01:00:00 __W_F__	PROG C 01:00:00 _____	PROG D 01:00:00 _____
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	----------------------------	----------------------------	--------------------------	--------------------------

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

11 Eleven

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #9 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00	_T_H_S_				PROG B 01:00:00	_W_F_				PROG C 01:00:00					PROG D 01:00:00				
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	--------------------	---------	--	--	--	--------------------	-------	--	--	--	--------------------	--	--	--	--	--------------------	--	--	--	--

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

12 Twelve

1 -			1																				1		
1 -			1																						
2 -				2																		2			
2 -				2																					
3 -					3																4				
3 -					3																3				
4 -						4														4					
4 -						4																			
4 -																				4					
4 -																				4					
4 -																				4					
4 -						4																			
5 -							5																		
5 -							5																		
5 -																			5						
5 -																			5						
5 -																			5						
5 -							5												5						

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #10 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #11 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #12 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #13 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #14 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #15 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #16 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #17 | 04/16/2025

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Repair Plan Page #18 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00	_T_H_S_					PROG B 01:00:00	_W_F_					PROG C 01:00:00						PROG D 01:00:00					
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	--------------------	---------	--	--	--	--	--------------------	-------	--	--	--	--	--------------------	--	--	--	--	--	--------------------	--	--	--	--	--

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

13 Thirteen

1 -																												
2 -																												
3 -																												
4 -																												
5 -																												
6 -																												
7 -																												
8 -																												
9 -																												
10 -																												
11 -																												
12 -																												
13 -																												

Totals			17	8	30	24	19	35	39	37	51	34	83	48	36	26	21	20	21	16	7	2	1					
--------	--	--	----	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	---	---	---	--	--	--	--	--

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #19 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00	T_H_S_	PROG B 01:00:00	W_F_	PROG C 01:00:00		PROG D 01:00:00	
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	--------------------	--------	--------------------	------	--------------------	--	--------------------	--

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	----------------------------	--------------	-------------

Totals			6						Totals
--------	--	--	---	--	--	--	--	--	--------

1 One

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #28 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #29 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #30 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #31 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #32 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #33 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #34 | 04/16/2025

[illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Coverage Plan Page #35 | 04/16/2025

K-Rain NoSub 11/04/2021	No Sensor Well	Water Meter Yes	Rotor Mins 11	Spray Mins 20	Drip Mins 30	PROG A 01:00:00	_T_H_S_	PROG B 01:00:00	_W_F_	PROG C 01:00:00	PROG D 01:00:00
----------------------------	-------------------	--------------------	------------------	------------------	-----------------	--------------------	---------	--------------------	-------	--------------------	--------------------

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	-------------------------------	--------------	-------------

13 Thirteen

1 -									
2 -									
3 -									
4 -									
5 -									
6 -									
7 -									
8 -									
9 -									
10 -									
11 -									
12 -									
13 -									

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	-------------------------------	--------------	-------------

Totals			6						Totals
--------	--	--	---	--	--	--	--	--	--------

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Page #36 | 04/16/2025


test

110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Zone Photos | Page #37

ZONE INSPECTION PHOTOS

Controller 1 - One
Zone 2: Zone Two
GPS: 29.5152399997, -95.1606691730




110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Zone Photos | Page #38

ZONE INSPECTION PHOTOS (continued)

Controller 1 - One
Zone 3: Zone Three
GPS: 29.5154400000, -95.1605178980



110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Zone Photos | Page #39


ZONE INSPECTION PHOTOS (continued)

Controller 1 - One
Zone 5: Zone Five
GPS: 29.5154400000, -95.1605063351

ID	Chapter	Category	Critique
#392	Ch 1	plot	STRENGTH - VOICE QUIR

ZONE INSPECTION PHOTOS (continued)

Controller 1 - One
Zone 9:



110 North
3102 Autumn Leaf Dr, Friendswood

#10945 INSPECTION
Zone Photos | Page #41

ZONE INSPECTION PHOTOS (continued)

Controller 1 - One
Zone 9:
GPS: 29.5154400000, -95.1605030817

