

110 North
3102 Autumn Leaf Dr, Friendswood

#50013 INSPECTION
Repair Plan Page #1 | 04/09/2026

[illegible]

1 One

[illegible]

2 Two

[illegible]

7 Seven

[illegible][illegible]

110 North
3102 Autumn Leaf Dr, Friendswood

#50013 INSPECTION
Coverage Plan Page #2 | 04/09/2026

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
Totals		2	2						Totals

1 One

1 Drip-Zone One			2						
-----------------	--	--	---	--	--	--	--	--	--

2 Two

1 -		2							
-----	--	---	--	--	--	--	--	--	--

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
Totals		2	2						Totals

ZONE INSPECTION PHOTOS

Controller 1 - One
Zone 1: Zone One
GPS: 29.5154400000, -95.1606400000

```
2584     function getEnhDetail($id,$mgr=null){
2585         $rs = $this->_db->query(Database::SELECT,$sql,$current());
2637         return array('all'=>$rs,'items'=>json_decode($rs['items']));
2638     } else {
2639         $rs = $this->_db->query(Database::SELECT,$sql);
2640         return $rs;
2641     }
2642 }
2643 }
2644 ?>
2645
```

3102 Autumn Leaf Dr, Friendswood

Zone Photos | Page #4

ZONE INSPECTION PHOTOS (continued)

GPS: 29.5153150000, -95.1604020000



110 North
3102 Autumn Leaf Dr, Friendswood

#50013 INSPECTION
Zone Photos | Page #5

ZONE INSPECTION PHOTOS (continued)

Controller 1 - One
Zone 2: Zone Two
GPS: 29.5153150000, -95.1604020000

