

#34824 INSPECTION
Repair Plan Page #1 | 06/03/2025

[illegible][illegible]

Walker, Elizabeth & Simon
3909 Balcones Drive , Austin

#34824 INSPECTION
Repair Plan Page #2 | 06/03/2025

CLOCK - STATION	CLEAN ADJUST NOZZLE	FIX ADJUST HEAD	NEW NOZZLE	NEW MP NOZZLE	4" SPRAY	6" SPRAY	12" SPRAY	SHRUB DRIP ADPTR	ROTOR	RIZER BREAK	CHECK VALVE	LATERA L LINE BREAK	MAIN LINE BREAK	1" VALVE ISSUE	1.5" VALVE ISSUE	2"+ VALVE ISSUE	2 WIRE DE- CODER	SOLE NOID	ZONE WIRE LOCATE	STICKE R	SIGN	JUMBO VALVE BOX	ROUND VALVE BOX	JUMBO COVER	ROUND COVER
-----------------	---------------------------	-----------------------	---------------	------------------	-------------	-------------	--------------	------------------------	-------	----------------	----------------	---------------------------	-----------------------	----------------------	------------------------	-----------------------	------------------------	--------------	------------------------	-------------	------	-----------------------	-----------------------	----------------	----------------

[illegible][illegible]

Walker, Elizabeth & Simon
3909 Balcones Drive , Austin

#34824 INSPECTION
Coverage Plan Page #3 | 06/03/2025

NoSub		Water Meter	Rotor Mins	Spray Mins	Drip Mins	PROG A _____	PROG B _____	PROG C _____	PROG D _____
-------	--	-------------	------------	------------	-----------	--------------	--------------	--------------	--------------

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
-----------------	--------------	---------------	--------------	----------------	----------------	-----------------	----------------------------	--------------	-------------

[illegible]

1 Rainbird inside garage

1 -Back left									
2 -Back left									
3 -Back									
4 -Not timer back									
5 -Back and front									
6 -Back by fence									
7 -Back									
8 -Front rt									
9 -Front rt									
10 -Front rt									
11 -Front mittle									
12 -Front mittle									
13 -Front entrance									
14 -Not timer front									
15 -Front									
16 -Front left garage									
17 -Front left garage									
18 -Front left garage									

Walker, Elizabeth & Simon
3909 Balcones Drive , Austin

#34824 INSPECTION
Coverage Plan Page #4 | 06/03/2025

[illegible]

CLOCK - STATION	LIFT HEAD	LOWER HEAD	MOVE HEAD	ADD 4" HEAD	ADD 6" HEAD	ADD 12" HEAD	ADD SHRUB DRIP ADPTR	ADD ROTOR	DESCRIPTION
Totals									

Walker, Elizabeth & Simon
3909 Balcones Drive , Austin

#34824 INSPECTION
Page #5 | 06/03/2025